

# JSK INDUSTRIES PVT. LIMITED

SILVASSA, INDIA.

## PROCESS FLOW CHART For AA Conductor (AAC)

Inspection 1 :  
Tensile Strength, Electrical Conductivity,  
Chemical Composition, Surface

Inspection 2 :  
Diameter, Tensile Strength,  
Resistance

Inspection 3 :  
Overall Diameter, Lay Ratio, Lay Direction, Surface

Inspection 4 : Winding

↓ Indicates Inspected and ACCPETED

⇒ Indicates Inspected and Not ACCPETED

