

JSK INDUSTRIES PVT. LIMITED

SILVASSA, INDIA.

PROCESS FLOW CHART For AAA Conductor (AAAC)

QC- 1

Tensile Strength, Electrical Conductivity, Dimension
Surface , Visual Inspection

Inspection 2 :

Diameter ,Tensile Strength,
Resistance

Inspection 3 :

Diameter ,Tensile Strength,
Resistance, Elongation

Inspection 4 :

Overall Diameter, Lay Ratio, Lay Direction, Surface

Inspection 5 :

Winding

↓ Indicates inspected & ACCEPTED
⇒ Indicates inspected & NOT ACCEPTED

